

I hereby certify that this correspondence is being deposited with the United States Postal Service, with sufficient postage, as first class mail in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on



4-8-2005

(Date of Deposit)

Dan L. Thompson, Reg. No. 54,490

Name of applicant, assignee, or
Registered Representative

Signature

4-8-2005

Date of Signature

Our File No. 10541-1976

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:

Kirk E. Neet

Patent No.: 6,826,823 B2

Issue Date: December 7, 2004

Serial No.: 10/767,022

Filing Date: January 29, 2004

For: AUTOMOTIVE ALTERNATOR STATOR
ASSEMBLY WITH RECTANGULAR
CONTINUOUS WIRE

Art Unit: 2834

Examiner: Tran Nguyen

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450


Attn: Certificate of Corrections Branch

Sir:

Please issue a Certificate of Correction for the above-identified patent to correct the errors listed on the accompanying PTO Form 1050. This request is being made pursuant to 35 U.S.C. § 254 and 35 U.S.C. § 255, since the errors comprise minor or typographical errors by the applicant or the PTO.

Enclosed herewith is a check for \$100.00 to cover the cost of applicant's errors. The Commissioner is hereby authorized to charge any additional fees required to Deposit Account No. 06-1500 (Visteon Global Technologies, Inc.). A duplicate copy of this sheet is enclosed.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Dan L. Thompson", is written over a horizontal line.

Dan L. Thompson
Registration No. 54,490
Attorney for Applicant

BRINKS HOFER GILSON & LIONE
P.O. Box 10395
Chicago, Illinois 60610
(312) 321-4200

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO : 6,826,823 B2
DATED : December 7, 2004
INVENTOR(S) : Kirk E. Neet

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the Title Page

In column 2, item (74), delete "Brink" and substitute --Brinks-- in its place.

In line 12, under "ABSTRACT", after "conductors" delete "." (period) and insert --alternate between radially inner and outer positions in each adjacent winding slot of the stator core.--.

MAILING ADDRESS OF SENDER:

Dan L. Thompson
BRINKS HOFER GILSON & LIONE
P.O. Box 10395
Chicago, Illinois 60610

PATENT NO. 6,826,823 B2

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.